



25.06.2010

Replacing air filter element

F 650 GS (K72, 0218/0228), F 800 GS (K72,

Management

Marketing

Sales
New MotorcyclesSales
Pre-owned Motorcycles

After Sales

Administration

Situation

On account of a fault in the production process, there is a possibility of cracks forming in the seals of the air filter elements. This process fault can be limited to the production period of the air filter elements from February 2009 up to and including November 2009.

The effects that can be produced by air filter elements damaged in this way include a detrimental effect on engine idle.

Each air filter element bears the production date in coded form (see photo).

Example: "8A11" stands for 2008, January 11 (so in this case the air filter element is not from the period during the production process was faulty):

- 8 = Production year 2008
- A = Production month January (A = January, B = February, ..., L = November, M = December (I is not used: J = September))
- 11 = Day of manufacture in production month



K72_R13055b

Photo: Air filter element with coded production date

Service Information No. 27/2010

Replacing air filter element

Each air filter element that has to be replaced bears one of the following codes:

9B16, 9B26, 9C05, 9C12, 9C19, 9C24, 9D01, 9D08, 9D15, 9D27, 9D28, 9E06, 9E19, 9E25, 9E27, 9F11, 9G01, 9G03, 9G06, 9G07, 9G14, 9G21, 9G22, 9G29, 9H06, 9H12, 9H19, 9J01, 9J07, 9J11, 9J14, 9J16, 9J29, 9K05, 9K12, 9K29, 9L24.

Motorcycles affected

See the local systems for technical campaigns (DMS, S-Gate, IWS, OSCAR Monitoring etc.) for a list of the motorcycles affected.

Series solution

On December 01, 2009 an optimised manufacturing process for the air filter elements was put in place in the supplier's plant.



Note

In the case of motorcycles with VINs outside the range of those affected that were nevertheless fitted ex-works with filter elements from the critical period, the filters have already been checked on the assembly line. In these cases replacement is not necessary.

Service solution

Before handing over a new motorcycle to its owner or when motorcycles possibly affected by this problem are next brought to the workshop, replace the air filter element (see attached work item 00 60 654 for details).



Note

The attached work item for the F 650 GS (K72, 0218) applies by analogy for the F 650 GS (K72, 0228) and F 800 GS (K72, 0219/0229) models.

Warranty processing

Defect code

00 13 20 00 00	Replacement, air filter element
----------------	---------------------------------

FRU numbers

00 60 654	Replacing air filter element (if applicable with installing/removing special tool, centre stand), 3 FRUs
-----------	--

Part number

13 71 7 679 366	Air filter element
-----------------	--------------------

Service Information No. 27/2010

Replacing air filter element



Note

Stocks of air filter elements from the critical production period (identification by list of date codes) must be scrapped entered in accounts by submission of a warranty application as follows:

Defect code: 90 00 03 23 00 (= elimination of stock)

Vehicle Identification Number: ZA00000

Warranty type: 2 (parts)

Odometer reading: 0 km

Date of first registration: Corresponds to date of scrapping

Contact

Carsten Gruetzmacher, UX-VA-3

Phone: +49 89 382 39017

Fax: +49 89 382 33220

E-mail: carsten.gruetzmacher@bmw.de

Recipients

ASIP portal (NSC / Importers)

Appendix

- Item No. 00 60 654

BMW MOTOCLUB CZ

